

**DATE:** September 11, 2003

**TO:** King County International Airport Tenants

distributed by e-mail and fax

FROM: Robert I. Burke, AAE, Airport Director

**SUBJECT: RWY 13R/31L Partial Closure** 

September 13, 2003 (Saturday)

KCIA/Boeing Field will be recabling the taxiway and runway lights between the A7 and B4 taxiway intersections on Saturday, September 13. This work will require closing the middle section of Runway 13R/31L.

The first 5500 feet of Runway 13R will be closed and will have a relocated threshold on September 13, 2003 (Saturday) from 07:30 - 19:30 (local time). Additionally, taxiway intersections A7 and B4 will be closed. The PAPI and REILs for Runway 13R/31L will be out of service during this time.

## Therefore...

- if 13R is active (south flow), there will be 4501 feet available for arrival and departure.
- if 31L is active (north flow), there will be 4501 feet available for departure and 3701 feet for arrival.

The continued cooperation of our aviation community is appreciated during this construction period.

Please check NOTAMs daily for changes.





DATE:

September 11, 2003

TO:

King County International Airport Tenants

Car 00

FROM:

Robert I. Burke, AAE, Airport Director

SUBJECT:

**Airport Security** 

U.S. Department of Homeland Security (DHS) has released an advisory to the aviation public in an effort to make sure continued vigilance is followed and suspicious actions reported to discourage any potential acts of terrorism at general aviation airports.

The DHS and the Transportation Security Administration (TSA) continue to monitor reports on potential terrorist threats in the United States. Based on a recent interagency review of available information, DHS remains concerned about Al-Qaeda's continued efforts to plan multiple attacks against the United States. These attacks may involve aviation. Therefore, the aviation community is encouraged to continue the same level of vigilance in following security procedures.

TSA wants to remind general aviation aircraft and airport operators to review the security measures contained in the Aircraft Owners and Pilots Association's (AOPA) Airport Watch Program materials. These may be accessed at www.aopa.org/airportwatch or by calling the KCIA Airport Operations Department at (206) 296-7332.

KCIA would like to encourage tenants and pilots to do their part in keeping our airport safe and secure by following these security recommendations:


- Secure unattended aircraft to prevent unauthorized use.
- Verify the identification of crew and passengers prior to departure.
- Verify that baggage and cargo are known to the persons on board.
- Wear proper airport identification and challenge persons not wearing proper identification.
- Direct increased vigilance to unknown pilots and/or clients for aircraft or helicopter rental or charters as well as unknown service/delivery personnel.
- Be alert to aircraft with unusual or unauthorized modifications.
- Be aware/alert of persons loitering in the vicinity of aircraft or air operations areas as well as persons loading unusual or unauthorized payload onto aircraft.
- Be aware/alert of persons who appear to be under stress or in the control of other persons.
- Be aware/alert of persons whose identification appears altered or inconsistent.
- Do not allow a vehicle or person to follow you inside the perimeter gate. This is a violation of King County Code Title 15. No piggybacking!

Report suspicious activity immediately to KCIA Airport Police at (206) 296-7392 or the TSA/AOPA Hotline at (866) GA-SECUR or (866) 427-3287.

ST.	LIME	DESTINAT	TION TEL/ID	NO.	MODE		PGS.	RE	SULT
*09/11	18:21	VALKERIE CORP	9p7643862	0360	SEQ. B'CAST	ECM	2	OK	00'47
<b>*09/11</b>	18:23	WA AUDIOLOGY	9p7644760	0360	SEQ. B'CAST	ECM		OK	00'36
<b>*</b> 09/11	18:24	WA AIR NAT'L GRD	9p7671550	0360	SEQ. B'CAST	ECM	1 1	OK	00'53
*09/11	18:25	NW SEAPLANES	9p7681947		SEQ. B'CAST	ECM	2	OK	01'57
*09/11	18:27	WESTERN METALS	9p7674539		SEQ. B'CAST	G3	2	OK	01'40
		WINGSALOFT	9p7679464		SEQ. B'CAST	ECM	2	OK	01'15
*09/11	18:31	MUS OF FLIGHT	9p7645707		SEQ. B'CAST	G3		OK	01'07
		S SEATTLE CC	9p7635156		SEQ. B'CAST	ECM	2	OK	01'20
		DUNCAN AVIONICS	9p7622997		SEQ. B'CAST	G3	2	OK	05'05
		GALVIN-MAIT BLD	9p7677662		SEQ. B'CAST	ECM		OK	01'15
		MENTE AVIATION	9p7633964		SEQ. B'CAST	ECM	2	OK	01'31
<b>*</b> 09/11	18:44	EXEC FLIGHT	9p7621561		SEQ. B'CAST	G3	2	OK	02'47
		OTTER CORP/JEM	9p7637761		SEQ. B'CAST	ECM	2	OK	04'23
		MJL AIRPARTNERS	9p7625732	ł .	SEQ. B'CAST	ECM		OK	01'57
		KGF AVIATION	9p7674047		SEQ. B'CAST	ECM	2		01'30
		INTELL VENTURES	9p7625481	1	SEQ. B'CAST	ECM	2	OK	01'29
		RAINIER AVIATION	9p7640142	l	SEQ. B'CAST	ECM	2	OK	03'02
*09/11			3,101011	ı	AUTO RX	ECM	1	OK	00'48
		AIRTECH	9p7675604	0360		G3	2	OK	02'06
		CASCADE FLIGHT	9p7671726	1	SEQ. B'CAST	ECM	2	OK	04'40
		OLDTHYMEAVIATION	9p7094323	1	SEQ. B'CAST	ECM	2	OK OK	02'22
		EMERGENCY MGMNT	54056		SEQ. B'CAST	ECM		OK	02 22
		SAFETY & CLAIMS	60514	0360		ECM ECM			
l .		SPEC_OPS/GUARD	64271		SEQ. B'CAST			OK	03'03
		AIRNET	8p6142381807p3947395		SEQ. B'CAST	ECM	2	OK	01'52
		HELIJETFLITEOPS	8p6042734644p3947395		SEQ. B'CAST	ECM		OK	00'59
±09/12		97689700	OP0012101011P0011000.		TRANSMIT	G3 G3		OK NG	01'42 00'39
							-	0	
<b>≉09/12</b>	08:04	97689700		0361	TRANSMIT	G3	0	NG 0	00'39
<b>*</b> 09/12	08:07	97689700		0362	TRANSMIT	G3	0	NG 0	00'40
<b>*</b> 09/12	08:10	97689700		0362	TRANSMIT	G3	0	NG	00'39
<b>*</b> 09/12	08:13	97689700		0363	TRANSMIT	G3	0	NG	00'39
<b>*</b> 09/12	08:17	97689700		0363	TRANSMIT	G3	0	NG	00'39
09/12	08:18	97689700		0364	TRANSMIT	G3	0	0 NG	01'03
09/12	08:22	97689700		0364	TRANSMIT	G3	0	0 NG	00'40
09/12	08:24	97689700		0365	TRANSMIT	G3	0	0 NG	00'39
09/12	08:28	97689700		0365	TRANSMIT	G3		0 NG	00'40
09/12	08:46	97689700			TRANSMIT	G3		0	
	08:49					49		NG 0	00'39
				U366	TRANSMIT		0	NG 0	00'00 #0018
09/12	08:51	97689700		0367	TRANSMIT	G3	0	NG 0	00'39
09/12	08:55	97689700		0367	TRANSMIT	G3	0	NG 0	00'41

\*\*\*\*\*\*\*\*\*\*\* MULTI TX/RX REPORT \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* TX/RX NO 0360 PGS. 2 TX/RX INCOMPLETE [\*018]9p7689458 HELIJET TRANSACTION OK [\*00179p7877931 SEATTLEJETSYC [\*002]9p7647102 AEROFLIGHT [\*003]9p7621223 AIR TRANSPORT [\*004]9p7630381 Airborne Express [\*005]9p5211865 Airlift NW [\*006]9p7626357 AIRPAC AIRLINES [\*007]9p7632036 AMERICAN AVIONIC [\*008]9p7636239 **AMERIFLIGHT** [\*009]9p7621158 AVIATION PARTNER [\*010]9p7633428 AVIATOR STORE [\*011]9p7647112 AVIATION TRNG [\*012]9p7620611 BAX GLOBAL [\*013]9p6555116 BOEING CO [\*014]9p764B124 CALIBER INSPECT [\*015]9p7674018 CLASSIC HELICOPT [\*016]9p7679333 GALVIN FLYING [\*019]9p7641904 KC JETCENTER [\*020]9p7680483 KIC AVIATION [\*021]9p7626046 LINDEAN AIRCRAFT [\*022]9p7641312 NAT'L AVIATION [\*023]9p7681715 NORDSTROM [\*024]9p7634837 PISTOL CREEK [\*025]9p7623542 SEA JET STREAM [\*026]9p7633320 SERVICE GRP [\*027]9p7630381 SOUND AERIAL SVY [\*028]9p7641986 TAG AVIATION [\*029]9p7674920 UPS [\*030]9p5536851 US CUSTOMS [\*031]9p5530190 US IMMIGRATIONS [\*032]9p7643862 VALKERIE CORP [\*033]9p7644760 WA AUDIOLOGY [\*034]9p7671550 WA AIR NAT'L GRD [\*035]9p7681947 NW SEAPLANES [\*036]9p7674539 WESTERN METALS [\*037]9p7679464 **WINGSALOFT** [\*038]9p7645707 MUS OF FLIGHT [\*039]9p7635156 S SEATTLE CC [\*040]9p7622997 DUNCAN AVIONICS [\*041]9p7677662 GALVIN-MAIT BLD [\*042]9p7633964 MENTE AVIATION [\*043]9p7621561 EXEC FLIGHT [\*044]9p7637761 OTTER CORP/JEM [\*045]9p7625732 MJL AIRPARTNERS [\*046]9p7674047 KGF AVIATION [\*047]9p7625481 INTELL VENTURES [\*048]9p7640142 RAINIER AVIATION [\*049]9p7675604 AIRTECH [\*050]9p7671728 CASCADE FLIGHT [\*051]9p7094323 OLDTHYMEAVIATION [\*052]54058 **EMERGENCY NOMNT** [\*053]80514 SAFETY & CLAIMS





DATE: September 11, 2003

TO: King County International Airport Tenants

distributed by e-mail and fax

[\*017]9p7689700

FROM: Robert I. Burke, AAE, Airport Director

SUBJECT: RWY 13R/31L Partial Closure

September 13, 2003 (Saturday)

KCIA/Boeing Field will be recabling the taxiway and runway lights between the A7 and B4 taxiway intersections on Saturday, September 13. This work will require closing the middle section of Runway 13R/31L.

The first 5500 feet of Runway 13R will be closed and will have a relocated threshold on September 13, 2003 (Saturday) from 07:30 - 19:30 (local time). Additionally, taxiway intersections A7 and B4 will be closed. The PAPI and REILs for Runway 13R/31L will be out of service during this time.

## Therefore...

- if 13R is active (south flow), there will be 4501 feet available for arrival and departure.
- if 31L is active (north flow), there will be 4501 feet available for departure and 3701 feet for arrival.

The continued cooperation of our aviation community is appreciated during this construction period.

Please check NOTAMs daily for changes.

**GUIDO PERLA**